


# DIGITUS Fiber blind plate

**AL-BP-LCD****EAN 4016032262879****Blindplate for LC duplex holes 100 pcs.**

Blindplate for LC duplex holes, 100 pcs.

- Used in termination boxes to cover ports not used

- Avoids dust and dirt in termination boxes
- Shipment: 100 pcs. per poly bag
- Material: plastic, black

**Logistics**

|                              | Number<br>(pcs) | Weight<br>(kg) | Depth<br>(cm) | Width<br>(cm) | Height<br>(cm) | cm³       |
|------------------------------|-----------------|----------------|---------------|---------------|----------------|-----------|
| Packaging Unit Carton        | 200             | 11.00          | 39.00         | 39.00         | 46.00          | 69,966.00 |
| Packaging Unit Inside        | 1               | 0.06           | 3.00          | 13.00         | 13.00          | 507.00    |
| Packaging Unit Single        | 1               | 0.06           | 4.00          | 17.00         | 10.00          | 680.00    |
| Net single without Packaging | 1               | 0.00           | 1.00          | 1.10          | 2.10           | 0.00      |

**More images:****Safety notes**

- Avoid direct contact with light sources: Fiber optic cables, especially those with active light sources such as lasers (e.g. in optical communication systems), can emit dangerous radiation that can damage
- eyes. Take care never to look directly into the light of an optical fiber, even if the light source is invisible to the naked eye.
- When working with fiber optic cables, especially during tests or when working with lasers, protective goggles should always be worn to protect against harmful radiation.
- When plugging and unplugging the cable, only grasp the plug and do not pull directly on the cable.
- Do not kink or crush: Fiber optic cables are sensitive to mechanical stress.
- To protect cables from physical damage, they should be laid in special ducts or with protective materials
- Keep cable connectors clean: Fiber optic cables are sensitive to dust and dirt. Even small particles on the connectors can severely impair the signal

- quality.
- Cables should not be used in environments with extremely high or very low temperatures. Observe the product information on the maximum operating temperature of the cable
  - Check cables regularly for visible damage such as cracks, kinks or signs of wear. Defective cables should be replaced immediately.

**EU responsible person**

EU based economic operator ensuring the product complies with the required regulations.

ASSMANN Electronic GmbH  
Auf dem Schüffel 3  
Lüdenscheid, Germany  
<https://www.assmann.com>  
[info@assmann.com](mailto:info@assmann.com)