Flare / solder adaptor type FSA

Introduction



With the flare / solder adaptor, type FSA, flare connections can be easily and reliably changed to solder connections.

The adaptor provides a method of joining that preserves the advantages of flare connections, i.e. easy and fast component replacement. At the same time, the flare / solder adaptor also provides the advantage of soldered joints, i.e. a high degree of tightness that prevents leakage. The adaptor contains no soft gaskets or O-rings which age and loose their sealing properties. Instead, it contains a copper seal which protects the flare collar against wear and fatigue. This copper seal ensures a thightness similar to that of soldered joints.

The copper seal must be changed each time the adaptor is dismantled for servicing flare components.

Frost grooves in the nut mean that the adaptors are suitable for wet environment, where the temperature is below the water freezing point. The nut cannot be loosened by encapsulated ice formation.

Application

The flare / solder adaptor, type FSA, is for use where servicing or some other factor makes a "genuine" solder connection impractical.

The adaptor can be used with advantage for components with flare connections on:

- pressure controls
- filter driers
- sight glasses, etc.

Standards

DIN 8964, which stipulates a maximum leak rate for refrigeration plant of $< 6.4 \times 10^{-6}$ mbar l/s at a differential pressure of 10 bar He.

The Dutch refrigeration standard (9.12.94/IBP 07d 94007, part 2.2.8.2.): "In variation to regulation 2.2.8.1 flanged joints, compression joints, quick-couplings, flat or conical packing or trapped O-rings will be permitted, but only if the packing or O-ring provide the seal and are replaced if the joint is disconnected and then remade.

Technical data


Refrigerants HFC, HCFC, CFC and other fluorinated refrigerants

Max. working pressure PB = 35 bar

Leak rate Max. 1 g / year

Max. tightening torque 1/4 in. / 6 mm: 20 Nm 3/8 in. / 10 mm: 30 Nm 1/2 in. / 12 mm: 60 Nm 5/8 in. / 16 mm: 100 Nm 3/4 in. / 18 mm: 200 Nm

Type designation



Ordering

Flare / solder adaptor set, 2 pcs.

Туре	Connection flare × solder in.	Code no. for 2 pcs.	Туре	Connection flare × solder mm	Code no. for 2 pcs.
FSA 22 FSA 33 FSA 44 FSA 516m	1/4 × 1/4 3/8 × 3/8 1/2 × 1/2 5/8 × 5/8	023U8002 023U8004 023U8006 023U8007	FSA 26m FSA 310m FSA 412m FSA 516m	1/4 × 6 3/8 × 10 1/2 × 12 5/8 × 16	023U8001 023U8003 023U8005 023U8007
FSA 66	$^{3/4} \times ^{3/4}$	023U8010	FSA 618m	$^{3/4} \times 18$	023U8009

Flare / solder adaptor set, 1 pc.


Туре	Connection flare × solder in.	Code no. for 1 pc.	Туре	Connection flare × solder mm	Code no. for 2 pcs.
FSA 22	1/4 × 1/4	023U8012	FSA 26m	1/4 × 6	023U8011
FSA 32	3/8 × 1/4	023U8022	FSA 36m	3/8 × 6	023U8021
FSA 33	3/8 × 3/8	023U8014	FSA 310m	3/8 × 10	023U8013
FSA 44	1/2 × 1/2	023U8016	FSA 412m	1/2 × 12	023U8015
FSA 516m	5/8 × 5/8	023U8017	FSA 516m	5/8 × 16	023U8017
FSA 66	3/4 × 3/4	023U8020	FSA 618m	3/4 × 18	023U8019

Accessories



Copper seal	Size	Number in packing	Code no.
B2 - 4 spec.	1/4 in. / 6 mm	300	011L4025
B2 - 6	² / ₈ in. / 10 mm	300	011L4017
B2 - 8	1/2 in. / 12 mm	200	011L4018
B2 -10	5/8 in. / 16 mm	100	011L4019
B2 -12	3/4 in. / 18 mm	50	011L4020

Dimensions and weights



Туре	Connection			1.		Weight
	Flare in.	Solder ODF	mm	L ₁	Stamping	kg
FSA 22	1/4	1/4 in.	39	7	MM	0.05
FSA 26m	1/4	6 mm	39	7		0.05
FSA 32 FSA 36m FSA 33 FSA 310m	3/ ₈ 3/ ₈ 3/ ₈ 3/ ₈	1/4 in. 6 mm ³ / ₈ in. 10 mm	39 50 50 50	7 7 9 9	MM MM	0.09 0.09 0.09 0.09
FSA 44	1/ ₂	¹ / ₂ in.	57	10	ММ	0.11
FSA 412m	1/ ₂	12 mm	57	10		0.11
FSA 516m	5/ ₈	5/8 in. / 16 mm	57	12	MM	0.14
FSA 516	5/ ₈	16 mm	57	14	MM	0.14
FSA 66	3/ ₄	³ / ₄ in.	68	14	MM	0.28
FSA 618m	3/ ₄	18 mm	68	14		0.28